

JUC, 28-3-2017, 15.15

present Harro, Des, Benito, Jonathan, Arpad

- Des: working on control system
- Jonathan: tested 64 Mz firmware, fringes in more or less right places but extra peak. Looking into this, probably phase going wrong, different from other firmwares
- Benito: will start looking at extended sources. Still many mixed-mode expts though.
- Harro: faulty time, was due to non-updating of EOP and such, needed for calculation of UVW. For some reason Des calculates UVW but does not keep them, like SFXC does. Now fixed.