JUC, 9-10-2015, 14.30, Arpad's room

Present Jonathan, Harro, Des, Arpad

Jonathan: re-did 5000/8000 byte packet tests, all seems fine. 32MHz: configuration works, some control code changes needed (2 to 1 mapping of BN to FN), should be done by Des next week. Some work on UB2, as Leon has returned to Vietnam (??) Temperatures can be read out for monitoring, adding voltages as well, I2C interfaces monitoring as well.

Des: made comparison of averaging (on UB - j2ms2), wrote small document. However, 2 baselines differ by 0.5 % or so, two others not at all. Need for further investigation, might be BN in funny state, might be packet loss.