JUC meeting, 15-10-2015, 11.00, Arpad's room

present Jonathan, Harro, Des, Arpad

Jonathan: been busy with UB2 tests.

Des: redoing comparison of averaging methods. Harro made histograms of packet counts, showed packet loss. Not a reserved machine, so not so strange. Ran test again, this time no packet loss but some subbands did not come through. This could be due to the re-programming after power outage on Tuesday.

Need some sort of sanity check: Des will implement a time-out check after app-reset. Jonathan can come up with diagnostic test. Combine both into script. Also mention what version is installed, 32 or 16MHz.