JUC, 20 August 2015, 11.00, Arpad's room

present Harro, Jonathan, Des, Arpad

Des: new control code done, seems to work ok. Simplified setup, infrastructure for multiple UBs, 32MHz. Not rolled out yet, only on Des's machine. Need old version to go back to in VSN, Des to take care of this. Averaging should be on by default.

Jonathan: 32MHz image ready for testing/breaking. Some timing errors, not too serious. Ad hoc tests could be done of 32MHz image with 16MHz data. Check timing, implement averaging on both UBs (not only one) and test again, compare to j2ms2 averaging. Des will do this.

Harro: fixed segmentation violation bug

Des: control code will need to be folded into eBob code. Should not be too hard, Des will investigate what exactly is needed for this.