

Engineering and Scientific aspects of the revitalizing and modernization of the ROT-54/2.6 Radio Telescope

*XXIII International Conference on Radio Telescopes and
Radio Interferometers (RR2020)*




RESULTS OF THE INSPECTION OF CARDAN
ASSEMBLY, AXIS, SUSPENSION, MOTORS,
EL. CURRENT SUPPLY CABLES ETC.

*HRAYR ABRAHAMYAN,
ARTUR ARZOUMANYAN, AVETIS SIMONYAN,
ARAM EREM*




YEREVAN, ARMENIA, 20:00 (UT+4),
SEPTEMBER 18TH, 2020

The Rotation System of The North South Axis (1)




The Rotation System of The North South Axis (2)



The DC Motor of the East West Axis



The Broken Connecting Rod (bracket) of the Cardan System of the East-West Axis (1)



The Broken
Cardan S

(bracket) of the
West Axis (2)



The Welding Part of the East West Axis

