

JUC, 9/12/2016, 11.00

present Jonathan, Harro, Des, Arpad

Harro: will test new fila10G firmware.

We should ask Benito to do imaging: Arpad will email

Need to run data through 16 and 32 MHz personalities, look at phase jumps, see if glitches are repeatable. Jonathan will run tests.

UDP reply looking better, but still only in 64MHz version, also new registers need transplanting.

JUC, 16/12/2016, 11.00

present Jonathan, Harro, Des, Arpad

Jonathan: length of UDP reply was wrong, has been fixed. Added all changes to 16MHz version. Does not meet timing, but not off by much. Running tests on both personalities, will look at EG87 data.

Not much more, all the others were in Rome and Benito is off on vacation