

JUC, 29-01-2016, 11.00, Arpad's room

present Jonathan, Harro, Des, Arpad

Jonathan: After power-down and ip-renumbering, some issues with gateway, Aribox did not get data, all fixed

Des: control code now starts up everything, except for UB. Should be fixed today, looks good. Some logistics needed for selecting input UB, output. Should hand this over to eBob.

After e next week: talk to operators, ask them to do some experiments. As soon as: have a go with Mark5 experiments.

Jonathan: found one possible bug causing strange cross correlations, need to compare simulations with different firmwares. UB2 going quite well, getting there.