

JUC, 09-03-2018, 11.00

present Harro, Benito, Jonathan, Arpad

Harro: not done anything. Des (ill) worked on the test rig, had to ask eBob to make some changes to DBBC simulator, which has been done.

Benito: made an image of calibrator, but with lost of data loss images are not really comparable with SFXC. Will redo correlation with Harro's packet spacing scheme.

Jonathan: put in new signal tap, put it on 0, then Des got ill. Paul mentioned that Surfnet warned for listening on port 11211. In fact UB listens on all ports above 1024. Jon will put it in restriction to actual used port number (64 in all). Erlang control code should decide to turn the reply on and off, no reason to keep it on while it is doing nothing at all.