

JUC, 26-01-2018, 11.00

present Mark, Jonathan, Benito, Arpad

Harro: sick

Last e-test: some issues with firewalling, 32 MHz broke immediately, 16 MHz did work, with fewer stations.

Are the 1000B packets a problem for JUC? Unknown, could be simulated but Jonathan has no time, Chinese visitors coming next week. Are 2000B packets possible at all? Also unknown.

Next week when Harro back, set up test after e. Test nr of stations, 1000 vs 2000, 16 vs 32 MHz.

Should get in touch with Gino, find out about issues with version with cornerturning, Harro or Arpad send email.

Benito: found that expt was 8MHz. Now looking for 16. Decision to go with 32, 16 a bit of a waste of time.

Outstanding: re-factored control code only for e, need merging. Des will only have time after February.

Burstiness of playback of recorded data. Not solved by Harro yet, needs to be done.