

JUC, 8-9-2017

present Jonathan, Harro, Des, Benito, Arpad

Jonathan: fixed registers, which count packets (1 sec off, all, all thrown away)

More simulations of the 64MHz FFT, found overflow. Also applying weights incorrectly when combining odd and even.

Des: made data available for Benito. Fixes of eBob seem to be fine, but these data predated this fix

Benito: will look at NME, extended source, next 2-3 weeks

4 sec problem. No progress?? Registers ok now, should be possible to check any drift between wall and correlator clock. Need formatter test, Des needs to make wall clock available somewhere (?), test vex file available, need some stations. Harro will email. If possible, after ToO ends on Monday.