

YUC meeting, August 19 2013, Arpad's room  
present: Jonathan, Des, Arpad, Harro via phone

Jonathan: 2 pols seems to work now, LL and RR fringe, LR and RL noise  
tried w 2, 4 and 8 stations

Only fringes on 4 stations so far, seems to follow particular stations....  
check?

Clock offset, all in re-compiled code, sec + frame nr, Des putting in model  
arguments. Tomorrow done?

VDIF reader needs mods, Harro or Des, also tomorrow. Then can check if  
lack of fringes due to offset. If not, different bug.

Jonathan has been looking into DSP builder.